

Reissued: 6-Dec-19

Model: Met-MF3	Date: 2-Oct-19	No.: RD0BL026a
----------------	----------------	----------------

Reissue

The items in ***bold italics*** were corrected or added, in ~~strike-out~~ were deleted.


Subject: How to overwrite temporary firmware		Prepared by: Yuusuke Taniguchi	
From: 2nd Tech Support Sec. Service Support Dept.			
Classification:	<input checked="" type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input checked="" type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Other (Firmware)	<input type="checkbox"/> Tier 2

In cases that a temporary ~~or customized~~ firmware (e.g. “D0BL1234A_LRC1234”) has been applied to a machine, a standard package firmware can NOT be applied in order to prevent any software failures caused by the mismatched combination of each firmwares.

In order to overwrite a temporary ~~or a customized~~ firmware and restore the machine to the standard version, follow the **PROCEDURE** below.

PROCEDURE

1. Enter the SP mode and change SP5-886-101 (Farm Update Setting: Skip LR Check) to “1”, and then tap the “#” key on the operation panel.



2. Press [EXIT] to leave the SP mode.
3. Execute the firmware update with “**package_01**” rather than “**Package(ALL)**”.
Note: If “Package(ALL)” is used, E86 appears and the update does not start.

Reissued: 6-Dec-19

Model: Met-MF3		Date: 2-Oct-19	No.: RD0BL026a	
Model	Region	Firmware Type	Version	P/N
MET-MF3abyz	GEN	package_01	2.20.04	D0BL5595
	CHN	TBA	TBA	TBA
MET-MF3cde	GEN	package_01	2.20.04	D0BN5595
	CHN	TBA	TBA	TBA

Note:

- If "Package(ALL)" is used to overwrite a temporary **or customized** firmware, E86 appears and the update does not start. (**E86: a temporary or customized firmware cannot be updated**).
- However, the machine will boot normally after turning the power OFF/ON.
- "Package(ALL)" and "package_01" are different only in the update specifications so the included firmwares themselves are same.
- Once the "package_01" applied to a machine and temporary **or customized** firmware is overwritten, "Package(ALL)" can be applied and the ARFU function will be available.
- SP5-886-101 previously set to "1", will automatically return to "0" after the update.
- The value of SP5-886-101 does not affected by turning the power OFF/ON.
- **Customized firmware can not be overwritten by the procedure above. The procedure will be announced separately.**

Reference:

Please refer to the following table regarding the update behavior in the case that the device is including temporary firmware.

Product	Package type	SP5886-101 is "0": (def)	SP5886-101 "1":
IM C series	Package_All	Update sequence does not start and E86 appears on the screen.	
	Package_01	Standard firmware (individual modules) is updated and Temporary firmware is NOT updated/overwritten.	Standard firmware and Temporary firmware is updated.
	ARFU	Update sequence does not start. Error code 29 is logged in SP7520-051-060.	
Predecessor Model (e.g. MP Cxx04)	Package_All	Standard firmware (individual modules) is updated and Temporary firmware is NOT updated/overwritten.	Standard firmware and Temporary firmware is updated.
	Package_01 (N/A)		
	ARFU	Standard firmware (individual modules) is updated and Temporary firmware is NOT updated/overwritten.	Standard firmware and Temporary firmware is updated.