

Menu

# RTB No.: RD0BL026a : How to overwrite temporary/customized firmware

Published 10/04/2019 03:24 AM | Updated 12/25/2019 02:35 AM | Answer ID 265403

QR Code

Access Level Tier 2

Other users found this answer helpful  Yes 0 [Rate this answer](#)[Print](#) [Notify Me](#)


## How to overwrite temporary/customized firmware

In cases that a temporary ~~or customized~~ firmware (e.g. "D0BL1234A\_LRC1234") has been applied to a machine, a standard package firmware can NOT be applied in order to prevent any software failures caused by the mismatched combination of each firmwares.

In order to overwrite a temporary ~~or a customized~~ firmware and restore the machine to the standard version, follow the **PROCEDURE** below.

### PROCEDURE

1. Enter the SP mode and change SP5-886-101 (Farm Update Setting: Skip LR Check) to "1", and then tap the "#" key on the operation panel.



2. Press [EXIT] to leave the SP mode.
3. Execute the firmware update with "**package\_01**" rather than "**Package(ALL)**".

**Note:** If "Package(ALL)" is used, E86 appears and the update does not start.

Model	Region	Firmware Type	Version	P/N
IM C3000/C3500/C2000/C2500	GEN	package_01	<b>2.20.04</b>	D0BL5595
	CHN	TBA	TBA	TBA
IM C4500/C5500/C6000	GEN	package_01	<b>2.20.04</b>	D0BN5595
	CHN	TBA	TBA	TBA



**Note:**

- If "Package(ALL)" is used to overwrite a temporary ~~or customized~~ firmware, E86 appears and the update does not start. (**E86: a temporary ~~or customized~~ firmware cannot be updated**).
- However, the machine will boot normally after turning the power OFF/ON.
- "Package(ALL)" and "package\_01" are different only in the update specifications so the included firmwares themselves are same.
- Once the "package\_01" applied to a machine and temporary ~~or customized~~ firmware is overwritten, "Package(ALL)" can be applied and the ARFU function will be available.
- SP5-886-101 previously set to "1", will automatically return to "0" after the update.
- The value of SP5-886-101 does not affected by turning the power OFF/ON.
- **Customized firmware can not be overwritten by the procedure above. The procedure will be announced separately.**

**Reference:**

Please refer to the following table regarding the update behavior in the case that the device is including temporary firmware.

Product	Package type	SP5886-101 is "0": (def)	SP5886-101 "1":
IM C series	Package_All	Update sequence does not start and E86 appears on the screen.	
	Package_01	Standard firmware (individual modules) is updated and Temporary firmware is NOT updated/overwritten.	Standard firmware and Temporary firmware is updated.
	ARFU	Update sequence does not start. Error code 29 is logged in SP7520-051-060.	
Predecessor Model (e.g. MP Cxx04)	Package_All	Standard firmware (individual modules) is updated and Temporary firmware is NOT updated/overwritten.	Standard firmware and Temporary firmware is updated.
	Package_01 (N/A)		
	ARFU	Standard firmware (individual modules) is updated and Temporary firmware is NOT updated/overwritten.	Standard firmware and Temporary firmware is updated.



Previously viewed answers

-  [RTB No.: RD0BL050 : Temporary Firmware overwrite function](#)

Products	Categories
EU	Documentation
Ricoh	RTB
Color Multifunction	Service Manual
IM C2000/A, C2500/A	Technical Information
IM C3000/A, C3500/A	Firmware
IM C4500/A, C5500/A, C6000	Firmware Updates
RexRotary	Troubleshooting
Color Multifunction	Error Messages/LED Light
IM C2000/A, C2500/A	Error Messages
IM C3000/A, C3500/A	
IM C4500/A, C5500/A, C6000	
Nashuatec	
Color Multifunction	
IM C2000/A, C2500/A	
IM C3000/A, C3500/A	
IM C4500/A, C5500/A, C6000	
Gestetner	
Color Multifunction	
IM C2000/A, C2500/A	
IM C3000/A, C3500/A	
IM C4500/A, C5500/A, C6000	